

Customer No.: 31561
Application No.: 10/065,343
Docket No.: 9527-US-PA

In The Specification

[0025] The DC plug 218 comprises an electrical connecting part 218a, an insulating part 218b and a stress-buffer structure 218c. The electrical connecting part 218a mates with the DC connector port 214, and the insulating part 218b and the stress-buffer part 218c partially cover the electrical connecting part 218a. A slot 220 is further externally defined on the insulating part 218b. When the DC plug 218 is inserted in the DC connector port 214, a rim of the opening 210 of the casing 208 engages by fitting with the slot 220 of the insulating part 218a to prevent a an unintentional separation of the DC plug 218 from the DC connector port 214 while allowing a relative rotation there between. Furthermore, the association of the stress-buffer structure 218c with the snap fit connection of the DC plug 218 substantially relieves wire winding-induced mechanical stresses such as wire torsions and/or internal tensions at the connecting zone between the DC plug 218 and the casing 202.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.